

TOTAL QUANTITIES FOR RECORD OF REPAIR #3

1A - Minimum Concrete	- EA =	38.00
1B - Edge Spall Repair	- LF =	20.75
1C - Surface Spall Repair	- SF =	64.74
1D - Overhead Spall Repair	- SF =	13.96
1E - Column, Beam, Kneewall, Wall	- CF =	6.38
1F - Full Depth Spall Repair	- SF =	5.44
1G - Post Tension Anchor Parking Deck	- CF =	0.00
1H - Post Tension Grout Pocket	- CF =	0.00
1I - Rust Spot Repairs	- EA =	2.00
1J - Stucco Replacement	- SF =	16.00
1K - Rout/Seal Crack Treatment	- LF =	7.67
1L - Rout/Seal (Parking Deck)	- LF =	0.00
1M - Hardwall Barricade *Interior 14LF	- EA =	0.00
1N - Exterior Barricade *SGD Opening	- EA =	0.00
1O - Softwall Barricade	- EA =	0.00
1P - Profilling/Leveling for Ponding	- SF =	0.00
1Q - Strip/Cleanup Loose Paint/20MIL	- SF =	0.00
1R - Miscellaneous Fasteners	- EA =	0.00
1S - Miscellaneous Sealants	- LF =	5.00
1T - Polyurethane Build Coat	- SF =	0.00
1U - Windowsill Spall Repair	- SF =	0.00

LEGEND:


COLUMN SPALL - CS
 COLUMN STUCCO - COLST
 MINIMUM CONCRETE - MIN
 OVERHEAD SPALL - OS
 RUST SPOT CEILING - RSC
 RUST SPOT DECK - RSD
 RUST SPOT WALL - RSW
 SET AHEAD - SA
 SET BACK - SB
 SURFACE SPALL - SS
 WALL SPALL - WS




SURFACE SPALL -SS



OVERHEAD SPALL -OS




FLOOR 1
AREA 2




N →

UNIT 401W




UNIT 301W



N →

UNIT 201W




N →

UNIT 417W


50" EDGE




UNIT 317W




UNIT 217W







UNIT 416




UNIT 317E




UNIT 316



UNIT 216




UNIT 217E




START OF PARKING DECK REPAIRS
INCLUDING EMBEDMENT AREAS

FAR SOUTH RAMP FROM PARKING DECK TO WALKWAY




FAR SOUTH SIDE OF PARKING DECK



8" X 5" X 2" CURB


SOUTHWEST CORNER
EMBEDMENT



8" X 7" X 4" CURB


BOTH LOOKING SOUTH

3RD EMBED ON WEST
SIDE




35" X 6" X 6" CURB

4TH EMBED ON WEST
SIDE




12" X 6" X 2" CURB

6TH EMBED ON WEST
SIDE



10" X 6" X 6" CURB


13TH EMBED ON WEST
SIDE



18" X 6" X 6" CURB


PARKING DECK RAMP NORTH SIDE RAILING

1ST EMBED




8" X 6" X 1" CURB

7TH EMBED



14" X 6" X 6" CURB

13TH EMBED



10" X 6" X 6" CURB

STARTING ON NORTH SIDE OF
RAMP (WESTERN SIDE OF DECK)


1ST



2ND



10" X 6" X 6"
CURB



3RD




4TH



13" X 6" X 6" CURB


5TH



11" X 6" X 6" CURB

STARTING ON NORTH SIDE OF
RAMP (WESTERN SIDE OF DECK)

7TH




26" X 6" X 6" CURB

8TH




9TH



14" X 6" X 6" CURB


10TH



9" X 6" X 6" CURB


STARTING ON NORTH SIDE OF
RAMP (WESTERN SIDE OF DECK)

13TH




13" X 6" X 6" CURB

14TH




16" X 6" X 6" CURB

15TH



9" X 6" X 6" CURB


20TH



11" X 6" X 6" CURB

STARTING ON NORTH SIDE OF
RAMP (WESTERN SIDE OF DECK)


21ST



10" X 6" X 6" CURB


FAR NORTH SIDE (STARTING
COUNTING FROM NW CORNER OF
PARKING DECK, #1 COUNTED AS
#21 ON PAGE 24

6TH




16" X 6" X 6" CURB

7TH




29" X 6" X 6" CURB

INBETWEEN 7TH
AND 8TH (6"X6"X6")




8TH





12" X 6" X 6" CURB

FAR NORTH SIDE (STARTING
COUNTING FROM NW CORNER OF
PARKING DECK, #1 COUNTED AS
#21 ON PAGE 24



CONTINUED FROM LAST PAGE



7" X 2" X 2" CURB


THE FAR NORTH LARGER WALKWAY(NOT AT
THE VERY END OF PARKING DECK)

6" X 6" X 6" CURB

8" X 7" X 6" CURB
+ 7" X 6" X 6" CURBVIEW THESE ON
THE NEXT PAGE (
THEY'RE
EMBEDEMENTS ON
THE OTHER SIDE
OF THE FENCE BY
THE SHUFFLE
BOARD COURT


NORTHWEST CORNER OF
SHUFFLE BOARD COURT

#1



14" X 6" X 6" CURB

#2



20" X 6" X 1" CURB

